

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From,
Sri.P.S.Anil Kumar. B.E. (FAC)
Executive Engineer (R&B)
(R&B) Division, Eluru,

To,
The Principal,
Siddhartha Quest CBSE School,
Door No.6-51,
Vatluru,
Eluru District,

Lr.No:259/Soundness Certificate/JA/2020, Dt: 24/3/2025.

Sir,


Sub:-Works (R&B) Division, Eluru- Siddhartha Quest CBSE School, Door No.6-51, Vatluru, in Eluru District, Soundness Certificate – Issued-Regarding.

Ref: -Request regarding the Soundness Certificate Siddhartha Quest CBSE School, Door No.6- 51, Vatluru, in Eluru District, Dt.22.02.2025

With reference to above, it is informed that the RCC Slab Roof Building, Siddhartha Quest CBSE School, Door No.6-51, Vatluru, in Eluru District, is structurally sound to run the classes for a period of one year i.e. from .20.03.2025 to 19.03.2026.

Enclose: Soundness Certificate.

Yours faithfully,


Executive Engineer (R&B)
(R&B) Division, Eluru.



SOUNDNESS CERTIFICATE

Sl.No.	Name of the school & address	School details
1	Name of school	:: Siddhartha Quest CBSE school, D.No. 6-51 , Vatluru, , Eluru - 534 007,
2	Name of the Management and phone number & Mail	:: Mobile - 62663 28012 e.mail -
3	Date of Inspection	:: AEE : 20.3.2025 :: DEE:
4	Year of construction	::
5	Type of Building	:: RCC slab roof building
6	Type of foundation footings, Basement and pling beam etc.,	:: Pile foundation
7	Present condition of foundation whether any settlement cracks are observed upto basement level	:: Sound
8	Souneness of superstructure whether any cracks out of plum, in walls noticed	:: Sound
9	soundness of RCC beam and lintels over openings	:: Sound
10	Condition of flooring	:: Sound
11	Condition of roof slabs, stair case slabs, cracks, leakages	:: Sound
12	Any other remarks which are required to ensure the structural soundness	:: This inspection certificate does not purport covering all the aspects of rthe work and designs.
13	Valid upto	:: 19.03.2026

CERTIFICATES

1) Certificate is issued based on the present physical condition of the building. The management is responsible for the structure deformities which occur during course of time in time.

2)Further the management has to take necessary precautions during natural calamities occur from time to time for the safety of the students (such as cyclones severe whether conditions, T.sumanimis, Earth quakes etc.,

3) Department is not responsible for any structures changes to the building in future course of time.

I do hereby ertify that, I have inspeted the school and found to structurally sound for running the school as the building is fot for the pu rpose of provding shelter from sun and rain.

M. G. S. K. 20/3/25
Asst.Exe.Engineer (R&B)
Section, Eluru.

// Countersigned//
N. N. 20/3/25
Dy.Executive Engineer (R&B)

"Counter Signed" Sub-Divn.No.I, Eluru.

24/3/25
Executive Engineer
(R&B) Division, ELURU
24/3/25

